

5/22/2024

Pebble Hill Plantation

Historic Resource Survey



Prepared by: Eric Menninger
EAM Preservation, LLC
Atlanta, Georgia

CONTENTS

Executive Summary	2
Glossary	3
Property Overview	5
Survey Approach	6
Methodology	6
Scoring	6
GIS Mapping.....	7
Historic District Overview	8
General Findings – At A Glance	9
Summary Conditions Assessment.....	10
Liability Issues	10
Suggested Preventive Maintenance tasks	11
Most At Risk Assets – adjusted scores	12
Most At Risk Assets – raw scores.....	14
Treatment Recommendations – Secretary of the Interior’s Standards for Treatment of Historic Properties...	19
MAP – All Assets	17
MAP - Assets Historic Status	18
MAP - Asset Revenue/Function Status	19
MAP - Overall Asset weighted Condition Rating	20
Conditions Assessment Survey – Full Results (unsorted)	21
Architectural Survey - Full Results (unsorted)	33

EXECUTIVE SUMMARY

Pebble Hill Plantation is a historic 3000+ acre property located in the southwest corner of Thomas County and eastern Grady County, Georgia. Established during the antebellum period by Thomas Jefferson Johnson, the plantation originally produced cotton, tobacco, and rice with the labor of 37 enslaved people. Post-Civil War, the property was transformed by Cleveland industrialist Howard Melville Hanna into a winter hunting resort, with significant building upgrades occurring between 1900 and the mid-1930s. Today, Pebble Hill operates as a public museum, educational facility, event venue, and residential rental provider, with additional revenue from timber operations.

Survey Overview

In April and May of 2024, a comprehensive survey was conducted on 105 built environment features at Pebble Hill. The survey, which excluded roads, culverts, bridges, and parking lots, involved photographing and examining each asset's exterior, using drone photography for aerial views, and physically assessing material integrity where possible. The building interiors were partially explored but not comprehensively assessed. The survey evaluated;

1. **Architectural Characteristics:** building type, construction system, roof design and materials, exterior cladding, fenestration, and foundation type.
2. **Materials Conditions:** evaluated current condition of roofing, dormers, site drainage, siding, trim, windows, porches, stairs, chimneys, foundations, and landscaping.
3. **Significance to operation:** categorize each asset for its current function (revenue generating, museum asset, National Register status or eligibility, use by operations or administration.)

The full survey data, including detailed scores, explanations and methodologies, can be accessed through a downloadable Excel spreadsheet. All surveyed assets were also mapped using ArcGIS and are available online at <https://storymaps.arcgis.com/stories/5ee8936d5eb54529ba2533e6aaa5e124>.

Conditions Assessment and Maintenance Recommendations

Several assets were identified as having hazardous conditions or needing immediate preventive and restorative maintenance. Examples include:

- **Main House Garage:** Severe water intrusion due to a large adjacent pine tree.
- **Piney Grove Missionary Baptist Church:** Cupola and steeple restoration needed.
- **Nurse/Carpenter/Fire Bldg.:** Advanced decay of first floor windows.
- **Brer Rabbit Hunters Cabin:** Decayed weatherboard siding and foundation piers.
- **Mule Feeder:** Failing roof rafters and shingles put this structure in jeopardy.
- **Dog Kennel Kitchen:** Endangered by plant growth on the building and a failing roof.
- **Pump House:** Debris covered roof and clogged downspouts need cleaning.

In conclusion, Pebble Hill Plantation embodies significant historical, architectural, and cultural value. The recent survey provides a detailed assessment of the property's current state, offering a foundation for preservation and maintenance efforts to ensure its continued legacy.

GLOSSARY

Abram Garfield: An architect from Cleveland, Ohio, and the son of President James Garfield. He is credited with many of the Georgian Revival designs at Pebble Hill.

Adjusted Scores: Scores calculated by combining raw scores with a valuation index based on an asset's significance, resulting in a balanced evaluation on a 1 to 10 scale.

Architectural Characteristics: Features of a building or structure, including type, design, and materials used. Specific characteristics recorded in the survey include type of resource, building type, roof design, and exterior cladding.

ArcGIS Database: A geographic information system used to store and display the geo-located assets from the survey, available online for viewing.

Assets: Different kinds of features on the property, such as buildings, structures, or sites.

Building Systems: Main components of buildings, including roofing, siding, windows, and foundations, which were evaluated for condition during the survey.

Cornice Design: The decorative molding along the top edge of a building, one of the architectural characteristics recorded in the survey.

Drone Photography: The use of drones to take aerial photographs, used to examine some assets from above during the survey.

Entablatures: The upper part of a classical building supported by columns, including the architrave, frieze, and cornice.

Exterior Cladding: The outermost layer of a building's exterior, such as siding or brick, recorded in the architectural characteristics.

Fenestration: The arrangement of windows and other openings on a building's exterior, an architectural characteristic recorded in the survey.

Foundation Type: The base upon which a building is constructed, recorded in the survey as part of the architectural characteristics.

Georgian Revival: An architectural style featuring classical details like columns and balanced fenestration, dominant at Pebble Hill.

GNAHRGIS: Georgia's Natural, Archaeological, and Historic Resources Geographic Information System, where Pebble Hill could be formally listed.

Historic Significance: The importance of an asset in terms of history and heritage, factored into the valuation index for adjusted scores.

Integrity of Materials: The condition and soundness of the materials used in buildings and structures, assessed during the survey.

Materials Conditions: The state of the materials used in buildings and structures, evaluated as part of the survey.

Methodology: The procedures and criteria used to conduct the survey, including architectural characteristics and materials conditions.

National Register of Historic Places: A federal list of sites significant in American history and culture. Thirty-four assets at Pebble Hill are listed another 30 are eligible for listing.


Non-contributing Assets: Assets that do not add to the historic significance of a property,

Plan Shape: The layout or floor plan of a building, an architectural characteristic recorded in the survey.

Raw Scores: Initial condition scores for building features, ranging from 1 (like new) to 5 (at risk or failing).

PROPERTY OVERVIEW

Pebble Hill Plantation is a 3000+ acre property located in the southwest corner of Thomas County and eastern Grady County, Georgia. The property was established in the antebellum period by Thomas Jefferson Johnson, one of the original settlers in the region. During the enslavement era, Pebble Hill produced cotton, tobacco, and rice with an enslaved population of thirty-seven souls according to the 1860 Federal Slave Schedule Census. Following the Civil War and Reconstruction, the largely derelict Pebble Hill was purchased by a wealthy northern industrialist from Cleveland, Ohio, Howard Melville Hanna, who began a conversion of the agricultural plantation into a winter hunting resort. Continued by his daughter and then grand-daughter, Elizabeth “Pansy” Poe, Pebble Hill was dramatically remade along the lines of an English country estate. While all the antebellum structures were lost or removed, Pebble Hill witnessed an expansive building upgrade between 1900 and the mid-1930s. In the subsequent decades, until its shift to a public museum, Pebble Hill was a working agricultural operation with a focus on equestrian and dairy activities. The property was listed as an historic district on The National Register of Historic Places in 1990. Today, it operates as a public museum, an educational facility, and an event venue. It also generates revenue from nearly two dozen residential rentals on the property and timbering operations.



Location and relative size of assets on Pebble Hill Plantation (map imagery courtesy of Esri)

SURVEY APPROACH

During April and May of 2024, a comprehensive site survey was conducted on all known built environment features at Pebble Hill. This survey examined 105 buildings, structures, and sites. It did not evaluate roads, culverts, bridges, or parking lots.

All the evaluated assets were examined and photographed on all sides from the exterior. Some were examined from above by means of drone photography. Where possible, surfaces were physically touched to determine the integrity of the materials. While some building interiors were explored and photographed, no comprehensive assessment of the interiors was conducted for this survey.

METHODOLOGY

The survey evaluated two broad categories of criteria:

- 1) architectural characteristics
- 2) materials conditions

The architectural characteristics were labeled and categorized and are designed to serve as an enduring resource. Should the stewards of the property decide to formally list Pebble Hill on Georgia's Natural, Archaeological, and Historic Resources Geographic Information System (GNAHRGIS), the information captured in this survey will be critical for completing their submission. The specific architectural characteristics recorded in this survey are:

- Type of Resource, National Register Listing or eligibility, Asset Category, Building Type, Number of Stories, Plan Shape, Construction System, Roof Design, Roof Materials, Cornice Design, Exterior Cladding, Fenestration, Foundation Type

The materials condition evaluation examined the main building systems visible from the exterior. Each component was assigned an individual score. Some of the asset types, such as "sites" and "structures," did not have all the features to evaluate. In these cases, an "NA" (non-applicable) is used in the database. The specific systems and features scored in this survey are:

- Roofing, Dormers, Roof drainage, Site Drainage, Siding, Trim, Windows, Porches, Stairs, Chimney, Foundation, Landscaping

SCORING

Each of the building features and components were scored on a scale of one to five where one equals "like new" and five equals "at risk or failing." Fractional values of these numbers were used while scoring. The 1-5 scores are labeled "Raw Scores" in the survey result.

These raw scores were then combined with a "valuation index" which was derived from the asset's significance to the larger operation. Significance was calculated by identifying the asset type


(building, structure, or site), the asset's current role (museum, venue, rental residence, admin, facilities or other), and the asset's historic significance. Each of these characteristics were ascribed a numeric value which was added to an assets raw score and then multiplied by 1.2. As a result, buildings or sites that serve as part of the museum or generate revenue, such as venues or residential rentals, or, are listed or eligible to be listed on the National Register, returned a higher overall value than assets used solely by the staff/facilities crew. Scores that utilize this multiplier calculus are referred to in the survey results as "Adjusted Scores."

The "adjusted scores" are tallied on a 1 to 10 scale where one equals "like new" and ten equals "at risk or failing." The resulting scores provide a balanced evaluation for every built-environment feature on the plantation. The exact mathematical calculations used for this survey are detailed on the "methodology" tab of the project spreadsheet.

The full excel spreadsheet is available in its native format at <https://www.eampreservation.com/file-share>. Users must log in with their email and then can download the full inventory. Select the Pebble Hill Plantation folder.

GIS MAPPING

All the assets in this survey were geo-located and imported into an ArcGIS database. A variety of filters and displays are used to present the information captured in the survey. The maps are available online at <https://storymaps.arcgis.com/stories/5ee8936d5eb54529ba2533e6aaa5e124> or click the image below.



HISTORIC DISTRICT OVERVIEW

Of the 105 assets identified on the property, seventy-nine are listed or eligible for listing on the National Register of Historic Places. Nineteen of the 105 assets are non-contributing due to their age (less than 50 years old) or loss of integrity from modifications.

Pebble Hill Plantation embodies a wealth of historic buildings, styles, techniques, and materials. The dominant architectural style is Georgian Revival with its focus on classical details like entablatures, pilasters, columns, and balanced fenestration. Much of this design is credited to Abram Garfield, a noted Cleveland, Ohio architect and son of the slain US President, James Garfield.

The building typologies are more diverse. These range from the concrete, steel and brick veneered construction of the public facing buildings such as the Main House, Dairy Barn Complex, and Waldorf to modified post and beam barns, pole barns, stick framed wood buildings and even a 19th century log cabin. The mass masonry Pump House and the wood framed Big Green Barn are two of the more impressive examples of the dominant building techniques found at Pebble Hill.

The materials used at Pebble Hill are very diverse. Wood, masonry, metal, and terracotta are widely employed. Roofing surfaces on the property illustrate this point perfectly. There are wood shingles, slate shingles, terracotta shingles, corrugated roofing, raised metal seam roofing and asphalt/composite shingles.

The property also includes a variety of structures, and ruins. Four of the sites mark the location of buildings lost to fire. Two of these have surviving chimney stacks. There are also three demarcated cemeteries on the property of which the Worker's (African American) Cemetery is the largest at approximately 20,000 square feet holding the graves of over 300 people. Much of the property is crisscrossed with formal brick walkways and ornamental walls. Like many of the buildings at Pebble Hill, these masonry elements express a high level of design and execution.

Much of the landscaping on the main grounds is credited to Ethelwyn Harrison, a landscape architect from Cleveland. Ms. Harrison designed a master plan for Pebble Hill in the early 1930s much of which survives including the Main House formal gardens with its diverse plantings and intricate walkways.



Classically influenced design is widespread.



The Pump House building exhibits the concrete, steel, brick veneer technique common on the property.



Diverse materials like the raised seam metal roofing on the Kitchen Garden Shed.



Formal masonry entrance to Worker's (African American) Cemetery.



Main House formal garden one of the formal landscapes


GENERAL FINDINGS – AT A GLANCE

Total assets on the property evaluated for this report:	105
Buildings:	89
Sites:	11
Structures:	5
Historic Significance	
Listed on National Register of Historic Places:	36
Eligible for listing if nomination updated:	43
Building/Structures/sites ineligible:	19
Asset Breakdown	
Museum related	31
Venue Related	5
Used by Facilities or Admin	30
Rental Residences	21
Other	18
Architectural Styles	
Vernacular	37
Classical Revival	38
Colonial Revival	8
Agricultural Revival	6
Formal Landscaping	6
Former Sites	5
No Academic Style	5
Building typology	
Masonry structures	32
Wood platform/Stick frame structures	43
Post and Beam	4
Log Cabin	1
Pole Barns	7
Other	2
Roof materials	
Asphalt/Composite	47
Slab clay tiles	11
Metal Corrugated	15
Metal Standing Seam	1
Slate	1
Wood	2
Mixed	12

SUMMARY CONDITIONS ASSESSMENT


LIABILITY ISSUES

The following list reflects hazardous situations observed in the public facing or rental assets.

	Uno Hill ADA Ramp	Base of handrail no longer secure
	Main House	Brick planter (northside) at risk of collapse
	Hadley Cottage	Northeast retaining wall at risk of collapse
	Log Cabin	Eastside entry stairs worn and spongy
	Mule Feeder Roof	Fractured rafters could lead to roof collapse
	Gatehouse East	Main entry walkway uneven brick surface
	Main House	ADA ramp is settling, inspect for structural integrity

SUGGESTED PREVENTIVE MAINTENANCE TASKS

These are areas where immediate intervention will prevent future decay or damage to the building.

	Clean gutters	Main House Sugar Hill House Courtyard Side of Visitors Center Noah's Ark	Clean and flush all gutters. Confirm the full run of downspout is clear of obstructions.
	Clean Roof	Pump House	Remove all organic debris from Pump House tray roof. Clean out downspout scuppers.
	Remove Foliage Growth	Kennel Kitchen Old Waldorf	Cut back and remove all vine and plant growth touching buildings

MOST AT RISK ASSETS – ADJUSTED SCORES

Scoring rubric: 1- 3 = “like new”, 4-6 = “maintenance required”, 7-9 = “asset at risk”, 10 = “failing”. A score above 7 indicates the likelihood that several components/systems of the asset are “at risk.” Only assets scoring 7 and above in aggregate are presented in this list. Full results can be viewed in the Excel file.

8	Main House Garage		8.63	This building is under siege from water intrusion at the cornice, windows, and foundation. Its long-term survival is reaching a critical flexion point. An essential first step for preservation would be removal of the large pine tree adjacent to the rear porch. Its proximity suffocates the structure with pine needles and branches and greatly limits evaporation thus contributing to material decay. This building should be stabilized against the elements. Organic matter should be removed from the roof surfaces, plywood covers should be installed on broken window openings and doors and a long-term strategy should be developed for the chronic basement flooding.
96	Piney Grove Missionary Baptist Church		7.96	The cupola and steeple need restorative care to protect the intricate woodwork and address the lean in the spire/bell tower. Also, the poor drainage on the west elevation is causing significant damage to the foundation and trim and the condition of the east side brick stairs are hazardous.
43	Nurse's/Fire/ Carpenter Bldg.		7.73	The first-floor windows have suffered serious water damage and need major reconstructive care. Also, evidence indicates drainage on the eastern side (front and rear) is not working properly causing water to pool along the foundation or flow back into carpenter's shop.
88	Brer Rabbit Hunters Cabin		7.63	The weatherboard siding and foundation piers are in poor condition and need repair.
10	School Teacher Cottage		7.58	The roof is in very poor condition and beginning to fail around the chimney area.
42	Electrical Shed		7.54	The roof has missing/damaged shingles which have rotted out the cornice in front and rear. Additionally, the door paint finish is in very poor condition.
99	Pet Cemetery		7.20	The perimeter fence is in poor condition and aggressive plant growth inside the perimeter in the southeast corner is obscuring and damaging grave markers.

(more >>>)

Pebble Hill Plantation – Historic Resource Survey

24	Main House		7.18	The entire structure needs a materials sensitive cleaning to remove the extensive organic growth on the mortar. Do not power wash. The box gutters need regular cleaning and storm windows need to be reattached on the west end, south side. Additionally, damage was noted on the north side loggia cornice beneath one of the internal downspouts. This area needs investigation and reconstruction. The metal frame windows lining the loggia are heavily rusted and need restorative care. The ADA ramp felt spongy and should be examined for structural integrity. Finally, several waist high planters on the north side near the east wing have fractured and pose a threat of collapse.
30	Visitor's Center		7.16	Several of the clay slab shingles are dislodged or missing on the turrets and turret dormers. Several of the corner trim boards and one window frame to the north of the entrance are showing serious material decay and need replacement. The gutter on the courtyard side is heavily clogged.
37	Stables		7.16	The apron roof in the courtyard needs paint refinishing as do several sections of the interior concrete ceiling. The courtyard side cornice shows some decay and should be examined for material failure.
39	Kitchen Garden		7.10	Numerous sections of the perimeter wall and perimeter wall concrete cap are fractured and need reconstruction with material sensitive mortar. The most significant areas are the northeast side/corner and the northwest side/corner.
40	Kitchen Garden Shed		7.07	A beautifully executed ornamental storage shed constructed with some of the oldest bricks on the property. The interior hallway needs restorative paint care. Some step cracks were observed on the west side exterior wall. The garden perimeter wall is separating from the structure at the rear.
25	East Wing		7.07	This handsome wing needs extensive mortar cleaning and paint maintenance on the woodwork.

MOST AT RISK ASSETS – RAW SCORES

This list isolates the most at risk buildings on the property regardless of their importance or significance to the organization. That means the scores were not adjusted for significance or importance. In the numbers displayed below, a 1 = like new, and a 5 or above = at high risk or failing. Only assets raw scores 3 and above are presented in this list.

Bldg. number	Building Name	Photograph	Raw Score	Adjusted Conditions Score	Issues
100	Dog Kennel Pens		5.30	5.80	3 of the pens are no longer fenced and the remaining dog houses need repair/restoration.
92	Abandon Cottage #2		4.68	6.18	The roof is still shedding water but failure is likely at eave within 5 years, shingles nearing end of life, Siding is solid in places but collapsed section in back, front - stair poor, chimneys overgrown, and tops are damaged. Site soon to be inaccessible due to growth.
91	Abandon Cottage #1		4.38	5.88	Roof still shedding water but failure likely at eave within 5 years, roof being covered with vine/plant growth, siding could still be reclaimed, Windows still in decent shape, front porch is solid, rear porch stairs collapsed, site almost totally overgrown, mortar decay observed on some piers, plant growth at top of chimney. Site Soon to be lost
87	White Turkey Cottage		4.19	5.69	Salvageable given neglect of structure, west side draining poorly, significant siding failure, some trim decay, all windows sashes removed, front porch collapsing, side porch floor and ceiling degraded, serious damage and decay to numerous piers, bldg. collapse possible. mortar recession observed, area immediately around structure could be cut-back/trimmed.

Pebble Hill Plantation – Historic Resource Survey

12	Workers (African American) Cemetery		4.00	5.00	Northeast corner of perimeter wall in danger of collapse, numerous headstones need resetting and cleaning.
14	Wild Garden		4.00	4.50	Not maintained but appears salvageable.
52	Mule Feeder		3.98	4.53	broken rafters, rotted shingles, roof failure causing draining within structure, fascia heavily decayed, piers solid with some minor organic growth, The retaining wall just west of structure showing a significant vertical crack and outward deflection.
99	Pet Cemetery		3.90	7.20	Perimeter fence rapidly decaying. Grounds needs cleaning, bush removal, tree pruning.
80	War Cottage #8		3.83	5.33	Roof shingles are largely intact but sheathing and fascia heavily degraded in places. site drains well, widespread paint failure and some material decay, the one visible window is in poor condition, others are probably similar, front porch collapsing, side porch floor and ceiling degraded, mortar appears sound, some pier tilt was observed, north chimney heavily encrusted with organic growth, chimney overgrown above base. (more>>>)

Pebble Hill Plantation – Historic Resource Survey

8	Main House Garage		3.83	8.63	Heavy material decay on lower courses and trim of interior courtyard dormers, porch in southwest heavily covered, Heavy organic growth on clay shingles, poor site drainage , evidence past flooding in east end basement, south side slope traps water against building, large pine tree is main culprit – should be removed, Heavy organic growth on brick exterior in places, broken sashes and glass, some casements intact, failing paint finishes throughout, Roof south side porch decaying, covered with pine needles, significant rising moisture on lower walls, receding mortar in foundational courses, flashing intact, western walkway covered w/organic growth,
65	Uno Hill Chix Coop west		3.73	5.23	Roofing is failing, poor site drainage, Siding in very poor condition, windows in poor condition, foundation intact, roof likely to collapse in next 2 years.
96	Piney Grove Missionary Baptist Church		3.66	7.96	West side draining poorly, Decay along lower course of western water table, cupola needs extensive paint restoration, steeple & belltower tilting, Side porch (vestry entrance) lower siding decay, mortar decay along western wall at grade, some mortar recession observed, front eastern brick steps are heavily decayed and pose hazard.
53	Dog Kennel Kitchen		3.59	5.59	main roof framing appears intact, no significant leaks visible inside but side shed roof already gone, heavy organic buildup on roofing surface, rotted cornice and collapsed soffit over shed section, frames and sash integrity appears good but heavy organic/plant growth on exterior, nano foundational settling observed, heavy plant growth rear of bldg. being overgrown by plants, plant growth will cause roof failure in near future.

Pebble Hill Plantation – Historic Resource Survey

84	Big Green Barn		3.54	6.44	Numerous roof shingles missing, gutter system no longer functional, removed or damaged and not replaced, battens missing, siding boards separating, material rotted out, especially on north side, Many windows shows extensive damage and missing elements, brick perimeter wall combined with piers for vertical load on interior, attic vents, not chimneys
13	Old Waldorf		3.52	6.92	heavy moss growth on roof, completely rotted fascia and soffit on east side, adj to chimney, Significant paint loss, organic growth, window frames good but heavy paint and glazing damage, Heavy cornice decay and foundational settling, some mortar decay at grade, heavy organic growth at top of chimney, no cap, North side of building being overgrown.
93	Barn near Sugar Hill House		3.48	6.38	Galvanized finish nearly gone on roof, adequate site drainage but decay noted on lower sections of siding, interior load bearing posts are damaged from insects, southwest corner pier collapsing, -
66	Uno Hill Chix Coop east		3.40	4.90	metal roof intact, but aged, site well drained, Siding at grade is failing, no sashes, just wire coverings, concrete block foundation is degrading in places, Surprisingly sound condition in spite of neglect.
88	Brer Rabbit Hunters Cabin		3.33	7.63	Shingles are in late life, significant needle/branch build up on rear facet of roof, drip edge worn but working, Most of the wood siding is showing significant wear or outright failure, The original wood windows have glazing failure, the aluminum are intact but poorly installed, Several piers significantly out of plumb, mortar good, chimney cap shows damage, CMU chimney stack also in good shape, large oak in northwest corner looming over western roof.

Pebble Hill Plantation – Historic Resource Survey

39	Kitchen Garden		3.30	7.10	Significant sections of perimeter wall decay with failure possible - most prevalent in northeast and northwest sections, also numerous damaged concrete pier caps most likely from oxide jacking due to re-bar.
42	Electrical Shed		3.24	7.54	shingles missing, ridge seam failing, heavy organic growth, drainage working in places but widespread cornice/pediment rot indicates roof failure in places, roof cornice and entablature failing, other elements damaged, broken window muntins, damaged glazing.
54	Dog Kennel Annex		3.24	5.24	roof framing appears intact, no significant leaks visible inside. heavy organic buildup on roofing surface, rotted and collapsed cornice/fascia on north side (rear), heavy paint decay everywhere, window integrity good but needs restorative cleaning, cracks visible on west floor, considerably less plant growth than adjacent kennel kitchen but high canopy tree (northeast corner) threatening structure.
59	Pump House		3.24	6.64	heavy organic accumulation within tray roof, components look good but organic matter clogging scuppers, decayed or damage wood elements at entry entablature, some rusted window elements and broken glass (pebble finish), large step crack at top of smoke stack, collapsing brick at connection of smoke stack to building, need to clean tray roof and prune trees along east side.
79	War Cottage #7		3.10	4.60	shingle surface good but roof sheathing failure in various places, one gable bracket has fallen, site drains well, widespread paint failure and some material decay of siding, windows show failing paint finish, broken glass panes, front screened porch in very poor condition (not safe), foundation sound, integrity good, heavy lime staining on shingles.


Pebble Hill Plantation – Historic Resource Survey

18	Family Cemetery		3.00	6.80	Many markers need material sensitive cleaning. (Soft bristle, D2 application)
15	Tea House (Ruins)		3.00	4.00	Not maintained but if foliage not cut back, most visual evidence will be obscured.


TREATMENT RECOMMENDATIONS – SECRETARY OF THE INTERIOR’S STANDARDS FOR TREATMENT OF HISTORIC PROPERTIES

The principles of historic building repair, as outlined by the Secretary of the Interior’s Standards for the Treatment of Historic Properties, emphasize the preservation of the building’s historical integrity and character. Key guidelines include prioritizing minimal intervention to maintain as much of the original materials and features as possible. Repairs should be conducted using techniques and materials that match the original in composition, design, and texture. When replacement of deteriorated elements is necessary, the new materials should be compatible with the old in terms of aesthetic and physical properties, ensuring that they do not damage or alter the building’s historic fabric. Additionally, any new additions or alterations should be clearly differentiated from the old, preserving the building’s historical authenticity while allowing for contemporary use. This approach balances the need to protect and preserve historical significance with the practical demands of maintaining functional and safe structures.

MAP – ALL ASSETS



5/22/2024



EAM Preservation

MAP - ASSETS HISTORIC STATUS

PHP - Asset Historic Status



5/22/2024

NRHP Status

Red square: Listed

Yellow square: Eligible

Cyan circle: Not listed/ineligible

World Imagery

Low Resolution 15m Imagery

High Resolution 60cm Imagery


High Resolution 30cm Imagery

Citations

4.8m Resolution Metadata



State of Florida, Maxar



SURVEY DATE: MARCH/APRIL 2024

PAGE 18

MAP - ASSET REVENUE/FUNCTION STATUS

PHP Asset Revenue/Function Status



5/22/2024

Revenue Category

Green Venue/Museum/Rental

Blue Admin/Facilities

White Other

World Imagery

Low Resolution 15m Imagery

High Resolution 60cm Imagery


High Resolution 30cm Imagery

Citations

4.8m Resolution Metadata



State of Florida, Maxar



SURVEY DATE: MARCH/APRIL 2024

PAGE 19

MAP - OVERALL ASSET WEIGHTED CONDITION RATING

PHP - Overall Asset Conditions Rating




5/22/2024

Overall Conditions Score

- Serious issue(s) warranting attention
- Some restorative care need
- Regular maintenance needed

- Currently sound & in good condition
- World Imagery
- Low Resolution 15m Imagery
- High Resolution 60cm Imagery

High Resolution 30cm Imagery
Citations
4.8m Resolution Metadata



SURVEY DATE: MARCH/APRIL 2024

PAGE 20

Pebble Hill Plantation – Historic Resource Survey

CONDITIONS ASSESSMENT SURVEY – FULL RESULTS (UNSORTED)

Bldgnumber	Building Name	Photograph	Adjusted Bldg. Score	Raw Bldg. Score	Roof score	Dormer Score	Drainage Score	Siding Score	Trim Score	Window Score	Porch Score	Chimney Score	Foundation Score	Landscaping Score
1	Noah's Ark		6.16	2.31	2.00	na	3.60	4.20	3.40	1.00	na	na	1.00	1.00
2	Maintenance Garage Annex #2		3.73	1.33	1.00	na	1.00	2.00	1.00	na	na	na	1.00	2.00
3	Maintenance Garage Annex #1		4.20	1.80	2.00	na	2.00	2.00	na	na	na	na	1.00	2.00
4	Maintenance Garage		5.46	2.06	3.50	2.00	3.00	2.00	2.00	2.00	na		2.00	2.00
5	Hadley Cottage Garage west		5.58	1.28	1.00	na	2.00	3.50	1.00	1.00			2.00	1.00
6	Hadley Cottage Garage east		5.58	1.28	1.00	na	2.00	3.50	1.00	1.00			2.00	1.00
7	Hadley Cottage		6.58	1.78	1.00	2.00	1.00	1.00	2.00	2.00	3.00		inaccessible	4.00
8	Main House Garage		8.63	3.83	3.50	4.00	4.00	3.50	4.00	3.80	4.00	3.00	4.00	4.50
9	School House		4.60	1.20	2.00		1.00	1.00	1.00	3.00	2.00		1.00	1.00

Pebble Hill Plantation – Historic Resource Survey

Bldgnumber	Building Name	Photograph	Adjusted Bldg. Score	Raw Bldg. Score	Roof score	Dormer Score	Drainage Score	Siding Score	Trim Score	Window Score	Porch Score	Chimney Score	Foundation Score	Landscaping Score
10	School Teacher Cottage		7.58	2.78	4.00	na	1.00	4.00	3.00	2.00	4.00	4.00	2.00	1.00
11	School Teacher Cottage Out bldg.		3.90	1.50	2.00	na	1.00	2.00	2.00	na	na	na	1.00	1.00
12	Workers (African American) Cemetery		5.00	4.00	na	na	na	na	na	na	na	na	na	4.00
13	Old Waldorf		6.92	3.52	4.20	na	5.80	3.90	3.00	3.80	4.00	2.00	2.00	3.00
14	Wild Garden		4.50	4.00	na	na	na	na	na	na	na	na	na	4.00
15	Tea House (Ruins)		4.00	3.00	na	na	na	na	na	na	na	na	na	3.00
16	Water Tank House		3.97	1.57	1.00	na	1.00	1.00	4.00	2.00	na	na	1.00	1.00
17	Tennis Court		4.85	1.00	na	na	na	na	na	na	na	na	na	1.00
18	Family Cemetery		6.80	3.00	na	na	na	na	na	na	na	na	na	3.00

Pebble Hill Plantation – Historic Resource Survey

Bldgnumber	Building Name	Photograph	Adjusted Bldg. Score	Raw Bldg. Score	Roof score	Dormer Score	Drainage Score	Siding Score	Trim Score	Window Score	Porch Score	Chimney Score	Foundation Score	Landscaping Score
19	Pool House		6.48	1.68	3.40	na	1.00	1.00	1.00	2.00	na	2.00	2.00	1.00
20	Swimming Pool		5.85	2.00	na	na	na	na	na	na	na	na	na	2.00
21	Shoe Shine east		6.34	2.04	2.00	na	2.00	2.00	2.00	3.30	na	na	2.00	1.00
22	Shoe Shine west		6.34	2.04	2.00	na	2.00	2.00	2.00	3.30	na	na	2.00	1.00
23	Arbor Trellis		5.60	2.25	na	na	3.00	2.00	na	na	na	na	2.00	2.00
24	Main House		7.18	2.38	2.70	2.00	4.10	2.80	2.00	3.40	2.70	1.00	1.00	2.10
25	East Wing		7.07	2.27	2.00	na	3.00	3.30	3.30	2.80	2.00	1.00	1.00	2.00
26	Main House Formal Garden		5.60	1.80	na	na	na	na	na	na	na	na	na	1.80
27	Site White Maids Cottage		2.00	1.00	na	na	na	na	na	na	na	na	na	1.00

Pebble Hill Plantation – Historic Resource Survey

Bldgnumber	Building Name	Photograph	Adjusted Bldg. Score	Raw Bldg. Score	Roof score	Dormer Score	Drainage Score	Siding Score	Trim Score	Window Score	Porch Score	Chimney Score	Foundation Score	Landscaping Score
28	Site Old Stables		2.00	1.00	na	na	na	na	na	na	na	na	na	1.00
29	Plantation Store (Country Store)		5.17	1.77	2.70	na	1.00	1.00	1.00	1.00	1.00	2.20	2.00	4.00
30	Visitor's Center		7.16	2.36	3.00	3.00	2.80	1.30	4.50	3.00	1.00	1.00	2.00	2.00
31	Cow Barn & Dairy		7.05	2.25	1.00	4.00	1.50	1.40	4.10	2.00	3.50	2.00	2.00	1.00
32	Garden Cottage		6.86	2.56	1.00	3.00	3.80	1.30	3.60	2.40	4.00	3.30	1.20	2.00
33	Admin Bldg.		4.77	1.87	1.00	na	2.00	1.20	3.60	2.40	1.00	2.40	1.20	2.00
34	Admin Garage		4.67	1.77	1.00	na	1.00	2.20	3.40	1.20	na	na	1.20	2.40
35	Carriage House Garage		5.13	2.23	1.00	na	2.40	2.20	4.30	2.40	na	na	1.20	2.10
36	Carriage House		6.79	1.99	1.00	2.00	2.40	2.40	3.50	2.10	2.30	na	1.20	1.00

Pebble Hill Plantation – Historic Resource Survey

Bldgnumber	Building Name	Photograph	Adjusted Bldg. Score	Raw Bldg. Score	Roof score	Dormer Score	Drainage Score	Siding Score	Trim Score	Window Score	Porch Score	Chimney Score	Foundation Score	Landscaping Score
37	Stables		7.16	2.36	2.20	2.00	2.40	2.30	3.80	2.30	3.00	na	1.20	2.00
38	Log Cabin (School)		6.76	1.96	1.20	na	1.00	3.90	2.00	1.20	3.70	2.40	1.20	1.00
39	Kitchen Garden		7.10	3.30	na	na	na	na	na	na	na	na	na	3.30
40	Kitchen Garden Shed		7.07	2.27	2.00	na	3.40	3.20	2.50	1.00	na	na	2.40	1.40
41	OC (Overflow) Cottage		6.70	1.90	2.70	1.00	1.00	1.00	1.40	2.30	2.00	4.10	2.40	1.10
42	Electrical Shed		7.54	3.24	4.30	na	2.00	3.00	5.00	4.40	na	na	2.00	2.00
43	Nurse's Office		7.73	2.93	3.20	3.00	3.30	2.40	2.20	4.70	na	2.10	3.50	2.00
44	Fire Engine House		7.73	2.93	3.20	3.00	3.30	2.40	2.20	4.70	na	2.10	3.50	2.00
45	Carpenter's Shop		7.73	2.93	3.20	3.00	3.30	2.40	2.20	4.70	na	2.10	3.50	2.00

Pebble Hill Plantation – Historic Resource Survey

Bldgnumber	Building Name	Photograph	Adjusted Bldg. Score	Raw Bldg. Score	Roof score	Dormer Score	Drainage Score	Siding Score	Trim Score	Window Score	Porch Score	Chimney Score	Foundation Score	Landscaping Score
46	Dog Hospital		6.77	1.97	2.80	na	1.20	2.40	2.70	2.70	na	na		2.00
47	Waldorf		7.00	2.20	1.20	2.00	1.20	1.70	2.50	4.40	3.00	2.20	1.00	2.80
48	Kennel Cottage		6.17	1.37	1.00	na	1.20	1.00	1.30	1.20	1.50	1.40	2.70	1.00
49	Old Dining Room Shed (restrooms)		6.00	1.20	2.00	na	1.00	1.00	1.20	1.00	na	na	1.20	1.00
50	Learning Center (Pipe Shed)		4.73	1.33	1.00	2.00	1.00	1.00	1.20	2.40	na	na	1.00	1.00
51	Blacksmith's Shop (Shed)		3.94	1.94	1.00	na	1.00	2.30	4.00	2.90	na	na	1.40	1.00
52	Mule Feeder		4.53	3.98	5.90	na	4.00	na	4.00	na	na	na	2.00	4.00
53	Dog Kennel Kitchen		5.59	3.59	5.40	na	2.70	2.50	5.00	3.80	na	3.30	2.00	4.00
54	Dog Kennel Annex		5.24	3.24	3.70	na	2.30	2.20	4.50	3.40	na	na	3.00	3.60

Pebble Hill Plantation – Historic Resource Survey

Bldg number	Building Name	Photograph	Adjusted Bldg. Score	Raw Bldg. Score	Roof score	Dormer Score	Drainage Score	Siding Score	Trim Score	Window Score	Porch Score	Chimney Score	Foundation Score	Landscaping Score
55	Ticket Booth		5.59	2.19	4.50	na	1.40	1.50	2.40	2.20	na	na	1.00	2.30
56	Gatehouse east		6.78	1.98	2.20	2.00	2.60	1.00	2.20	2.10	1.00	2.00	1.00	3.70
57	Gatehouse garage		6.41	1.61	2.10	na	1.20	1.00	2.00	2.00	na	na	1.00	2.00
58	Gatehouse west		6.76	1.96	3.00	2.00	2.80	1.00	2.60	2.20	1.00	2.00	1.00	2.00
59	Pump House		6.64	3.24	2.90	na	3.80	3.50	3.60	2.50	na	3.80	2.00	3.80
60	Big Barn Cottage		5.23	1.43	2.00	2.00	1.30	1.50	1.00	1.30	1.00	1.20	2.00	1.00
61	Oak Post New Stable		3.48	1.08	1.00	na	1.00	na	1.40	na	na	na	1.00	1.00
62	Oak Post Storage		4.59	1.69	2.60	na	1.00	1.20	3.00	na	1.00	na	2.00	1.00
63	Oak Post Stable (old)		5.23	2.33	2.90	na	1.00	3.30	3.20	na	na	na	2.60	1.00

Pebble Hill Plantation – Historic Resource Survey

Bldgnumber	Building Name	Photograph	Adjusted Bldg. Score	Raw Bldg. Score	Roof score	Dormer Score	Drainage Score	Siding Score	Trim Score	Window Score	Porch Score	Chimney Score	Foundation Score	Landscaping Score
64	Oak Post Barn		5.07	2.17	2.50	na	1.00	2.80	2.40	na	na	na	2.30	2.00
65	Uno Hill Chix Coop west		5.23	3.73	5.90	na	3.50	3.60	4.40	3.40	na	na	3.30	2.00
66	Uno Hill Chix Coop east		4.90	3.40	3.60	na	3.50	3.60	4.40	3.40	na	na	3.30	2.00
67	Uno Hill Maintenance #1		4.12	1.72	2.20	na	1.20	2.50	2.20	na	na	na	1.20	1.00
68	Uno Hill Maintenance #2		4.62	2.22	2.20	na	3.20	2.60	3.10	na	na	na	1.20	1.00
69	Uno Hill Maintenance #3		5.35	2.95	2.20	na	2.40	2.90	4.50	na	na	na	2.70	3.00
70	Uno Stable (kitchen)		5.30	1.50	1.10	na	1.30	1.20	1.20	1.00	1.00	na	1.20	4.00
71	Uno Stable (venue)		5.34	1.54	1.00	na	1.00	1.70	2.20	1.00	1.00	2.80	1.20	2.00
72	Uno Stable pump house		4.36	1.96	2.10	na	2.40	2.80	2.20	2.00	na	na	1.20	1.00

Pebble Hill Plantation – Historic Resource Survey

Bldgnumber	Building Name	Photograph	Adjusted Bldg. Score	Raw Bldg. Score	Roof score	Dormer Score	Drainage Score	Siding Score	Trim Score	Window Score	Porch Score	Chimney Score	Foundation Score	Landscaping Score
73	War Cottage #1		6.61	2.31	2.40	na	2.20	3.40	3.20	2.00	2.70	1.50	2.40	1.00
74	War Cottage #2		6.93	2.63	2.40	na	1.40	3.50	3.50	3.80	na	1.60	2.10	2.70
75	War Cottage #3		6.53	2.23	2.30	na	2.20	2.70	2.40	3.80	2.00	1.30	2.40	1.00
76	War Cottage #4		6.63	2.33	2.20	na	2.20	2.30	2.90	3.40	2.00	2.80	2.20	1.00
77	War Cottage #5		6.28	1.98	2.90	na	2.20	2.20	2.20	2.80	1.00	1.30	2.20	1.00
78	War Cottage #6		6.58	2.28	2.90	na	2.50	2.30	2.60	2.20	1.00	2.40	2.20	2.40
79	War Cottage #7		4.60	3.10	4.40	na	1.30	3.70	3.60	3.40	5.00	2.20	2.20	2.10
80	War Cottage #8		5.33	3.83	3.80	na	2.60	4.30	5.10	4.90	5.00	3.90	2.70	2.20
81	Peachtree Cottage		6.27	1.97	3.00	na	2.20	1.20	1.20	1.20	2.00	2.10	2.60	2.20

Pebble Hill Plantation – Historic Resource Survey

Bldgnumber	Building Name	Photograph	Adjusted Bldg. Score	Raw Bldg. Score	Roof score	Dormer Score	Drainage Score	Siding Score	Trim Score	Window Score	Porch Score	Chimney Score	Foundation Score	Landscaping Score
82	Big Pine Wood Cottage		6.22	1.92	1.40	na	1.20	2.40	2.30	2.50	1.00	2.20	2.10	2.20
83	Big Green Shed		5.20	2.30	2.10	na	1.20	4.00	4.00	3.40		2.80	2.20	1.00
84	Big Green Barn		6.44	3.54	3.80	2.00	4.70	4.80	4.60	5.00	na	3.40	2.60	1.00
85	Big Green Farmer's Cottage		6.41	2.11	2.20	na	1.20	2.40	2.10	2.60	3.00	2.20	2.10	1.20
86	Big Green Farmer's Cottage Shed		6.44	2.14	2.90	na	1.20	2.70	2.30	2.30	na	2.50	2.00	1.20
87	White Turkey Cottage		5.69	4.19	2.40	na	3.90	4.70	4.20	5.00	5.00	3.70	4.90	3.90
88	Brer Rabbit Hunters Cabin		7.63	3.33	2.80	na	1.70	4.90	2.90	3.80	3.20	2.90	4.50	3.30
89	Sugar Hill Barn (venue)		6.18	2.38	2.50	3.60	1.20	3.80	3.90	na	1.40	na	1.40	1.20
90	Austin House Ruins		1.90	1.40	na	na	na	na	na	na	na	na	na	1.40

Pebble Hill Plantation – Historic Resource Survey

Bidnumber	Building Name	Photograph	Adjusted Bldg. Score	Raw Bldg. Score	Roof score	Dormer Score	Drainage Score	Siding Score	Trim Score	Window Score	Porch Score	Chimney Score	Foundation Score	Landscaping Score
91	Abandon Cottage #1		5.88	4.38	3.80	na	5.00	4.50	4.80	3.60	3.90	3.70	4.20	5.90
92	Abandon Cottage #2		6.18	4.68	4.50	na	4.90	4.80	4.90	4.50	4.30	3.80	4.50	5.90
93	Barn near Sugar Hill House		6.38	3.48	3.70	na	2.40	3.90	4.20	na	-	na	4.50	2.20
94	Sugar Hill House		6.90	2.60	2.80	na	3.80	2.90	1.80	2.20	2.20	2.40	1.40	3.90
95	Sugar Hill House Garage		5.07	1.27	1.20	na	1.20	1.30	1.30	1.30	na	na	1.20	1.40
96	Piney Grove Missionary Baptist Church		7.96	3.66	2.40	4.70	4.50	3.90	4.50	3.10	3.10	3.40	2.80	4.20
97	Piney Grove Fellowship Hall		6.45	2.65	2.80	na	3.50	2.40	3.30	2.40	2.00	na	2.40	2.40
98	Piney Grove Maintenance Shed		4.40	2.00	2.00	na	2.00	2.00	2.00	2.00	2.00		4.00	2.00
99	Pet Cemetery		7.20	3.90	na	na	na	na	na	na	na	na	na	3.90

Pebble Hill Plantation – Historic Resource Survey

Bldgnumber	Building Name	Photograph	Adjusted Bldg. Score	Raw Bldg. Score	Roof score	Dormer Score	Drainage Score	Siding Score	Trim Score	Window Score	Porch Score	Chimney Score	Foundation Score	Landscaping Score
100	Dog Kennel Pens		5.80	5.30	na	na	na	na	na	na	na	na	na	5.30
101	Sugar Hill Barn (venue) garage		4.71	2.31	2.40	na	2.50	2.50	2.30	2.10	na	na	2.30	2.10
102	Sugar Hill Barn (venue) pump house		4.83	2.43	2.40	na	2.50	2.50	2.80	na	na	na	2.30	2.10
103	Sugar Hill House Pump House		4.73	2.33	2.30	na	2.50	2.80	2.40	2.30	na	2.20	2.40	1.70
104	Sugar Hill House 3 Bay Garage		6.79	2.49	2.80	na	2.40	2.50	3.10	2.40	na	na	2.50	1.70
105	Sugar Hill House Storage Shed		5.39	2.49	2.80	na	2.40	2.50	3.10	2.40	na	na	2.50	1.70

Pebble Hill Plantation – Historic Resource Survey

ARCHITECTURAL SURVEY - FULL RESULTS (UNSORTED)

Bldg number	Building Name	Photograph	NRHP	Architectural Style	Number of Stories	Plan Shape	Construction System	Roof Design	Roof Material	Eave	Ext. Wall Material	Type of cladding	Window Material	Type	Foundation Materials	Type of foundation	Driveway	Landscape features
1	Noah's Ark		LISTED	No Academic Style	1 to 1 1/2 story	Shape of a boat	wood frame	Gable	Mixed	Boxed Cornice	Wood	Weather board			Concrete (poured)	Slab	No	Lawn; trees;
2	Maintenance Garage Annex #2		NO	No Academic Style	1 to 1 1/2 story	rectangle	pole barn	Shed roof	Metal corrugated	Exposed rafters no fascia	Metal	Sheet material			Concrete (poured)	Slab	Asphalt	trees
3	Maintenance Garage Annex #1		NO	No Academic Style	1 to 1 1/2 story	rectangle	CMU	Hip	Metal corrugated	Boxed Cornice	CMU	Running bond			Concrete (poured)	Slab	Asphalt	working environment
4	Maintenance Garage		LISTED	Classical Revival	1 to 1 1/2 story	L shape	Mass masonry	Hip & Valley	Slate	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Brick	Continuous	Concrete	ornate wall
5	Hadley Cottage Garage West		Eligible	Classical Revival	1 to 1 1/2 story	L shape	Mass masonry	Hip	Asphalt/Composite	brackets	Brick	Common bond	Wood	Casement	Brick	Continuous	Concrete	yard
6	Hadley Cottage Garage east		Eligible	Classical Revival	1 to 1 1/2 story	L shape	Mass masonry	Hip	Asphalt/Composite	brackets	Brick	Common bond	Wood	Casement	Brick	Continuous	Concrete	yard
7	Hadley Cottage		LISTED	Classical Revival	2 to 2 1/2 story	rectangle	platform, wood framed	Cross Gable	Asphalt/Composite	Boxed Cornice	Brick	Running bond	Wood	Double Hung	Brick	Continuous	No	shrubs, hedge, retaining trees,
8	Main House Garage		LISTED	Classical Revival	2 to 2 1/2 story	U - shaped	Mass masonry	Cross Gable	Mixed	Boxed Cornice	Brick	Common bond	Wood	Mixed	Brick	Continuous	Concrete	walkways, bushes, shrubs, concrete
9	School House		LISTED	Vernacular	1 to 1 1/2 story	T-shaped	platform, wood framed	Hip & Valley	Asphalt/Composite	Exposed rafters w/fascia	Wood	Board & Batten	Wood	Double Hung	Brick	Piers w/in-fill	Gravel	
10	School Teacher Cottage		LISTED	Vernacular	1 to 1 1/2 story	Square	platform, wood framed	Hip	Asphalt/Composite	Exposed rafters w/fascia	Wood	Board & Batten	Wood	Double Hung	Brick	Piers w/ no in-fill	No	
11	School Teacher Cottage Out bldg.		NO	Vernacular	1 to 1 1/2 story	Square	Stick framed	Hip	Asphalt/Composite	Exposed rafters w/fascia	Wood	Board & Batten			Concrete (poured)	Continuous	No	
12	Workers (African American)		LISTED	Formal Landscaping			na										No	
13	Old Waldorf		LISTED	Colonial Revival	1 to 1 1/2 story	Square	platform, wood framed	Hip	Asphalt/Composite	Boxed Cornice	Wood	Weather board	Wood	Double Hung	Brick	Piers w/in-fill	No	trees
14	Wild Garden		Eligible	Former site			na										No	ponds; walkway bridges
15	Tea House (Ruins)		LISTED	Former site			na										No	remnant chimney stack,
16	Water Tank House		NO	Colonial Revival	1	rectangle	CMU	Gable	Asphalt/Composite	Boxed Cornice	CMU	Running bond	Wood	Casement	Other	Continuous	No	grass, adj ivy covered wall
17	Tennis Court		LISTED	Classical Revival			na										No	perimeter wall, coping, fountain gravel
18	Family Cemetery		LISTED	Formal Landscaping			na										No	walkway; altar
19	Pool House		LISTED	Classical Revival	1 to 1 1/2 story	rectangle	Mass masonry	Tray	Mixed	parapet	Brick	Common bond	Wood	Double Hung	Brick	Continuous	No	tombs, extensive plantings; shrubs, brick masonry pool
20	Swimming Pool		LISTED	Classical Revival			na										No	deck, railings, sitting areas,

SURVEY DATE: 11/01/2014 BY: JEFFREY

PAGE 30

Pebble Hill Plantation – Historic Resource Survey

Bldg number	Building Name	Photograph	NRHP	Architectural Style	Number of Stories	Plan Shape	Construction System	Roof Design	Roof Material	Eave	Ext. Wall Material	Type of cladding	Window Material	Type	Foundation Materials	Type of foundation	Driveway	Landscape features
21	Shoe Shine east		Eligible	Classical Revival	1 to 1 1/2 story	octagon	Stick framed	Hip	Asphalt/Composite	Boxed Cornice	Wood	Weather board	Wood	Casement	Brick	Continuous	No	lawn; gravel walkway
22	Shoe Shine west		Eligible	Classical Revival	1 to 1 1/2 story	octagon	Stick framed	Hip	Asphalt/Composite	Boxed Cornice	Wood	Weather board	Wood	Casement	Brick	Continuous	No	lawn; gravel walkway
23	Arbor Trellis		Eligible	Classical Revival	1 to 1 1/2 story	T-shaped	masonry columns, wood trellis								Concrete (poured)	Piers w/in-fill	No	plantings; reflecting pool, ornate brick
24	Main House		LISTED	Classical Revival	2 to 2 1/2 story	complex/Compound	Mass masonry, concrete floors, brick veneer	Mixed	Mixed	Boxed Cornice	Brick	Running bond	Mixed	Mixed	Concrete (poured)	Slab	Gravel	walkways, ornamental bushes, shrubs, plantings, abundant
25	East Wing		LISTED	Classical Revival	1 to 1 1/2 story	Square	Mass masonry, concrete floors, brick veneer	Cross Gable	Mixed	Boxed Cornice	Brick	Running bond	Wood	Double Hung	Concrete (poured)	Continuous	No	plantings, extensive
26	Main House Formal Garden		LISTED	Formal Landscaping			na										No	plantings, extensive
27	Site White Maids Cottage		LISTED	Former site			na										No	nothing left
28	Site Old Stables		LISTED	Former site			na										No	
29	Plantation Store (Country Store)		LISTED	Classical Revival	1 to 1 1/2 story	T-shaped	Mass masonry	Cross Gable	Clay flat slab	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Brick	Continuous	No	several high canopy trees, walkways, shrubs on
30	Visitor's Center		LISTED	Classical Revival	2 to 2 1/2 story	L shape	Mass masonry, concrete floors, brick veneer	Cross Gable	Mixed	Boxed Cornice	Brick	Common bond	Wood	mixed	Brick	Continuous	No	walkway, bushes, lawn
31	Cow Barn & Dairy		LISTED	Classical Revival	2 to 2 1/2 story	U - shaped	Mass masonry, concrete floors, brick veneer	Mixed	Mixed	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Brick	Continuous	No	courtyard formally landscaped
32	Garden Cottage		Eligible	Classical Revival	2 to 2 1/2 story	rectangle	Mass masonry, concrete floors, brick veneer	Gable	Mixed	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Brick	Continuous	No	walkways, shrubs
33	Admin Bldg.		Eligible	Classical Revival	2 to 2 1/2 story	T-shaped	Mass masonry, concrete floors, brick veneer	Hip & Valley	Mixed	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Brick	Continuous	Gravel	walkways, shrubs, low canopy tree shrubs, low
34	Admin Garage		Eligible	Classical Revival	1 to 1 1/2 story	Square	Mass masonry	Gable	Asphalt/Composite	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Brick	Continuous	Gravel	canopy trees along west
35	Carriage House Garage		Eligible	Classical Revival	1 to 1 1/2 story	Square	Mass masonry	Gable	Asphalt/Composite	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Brick	Continuous	Gravel	hedge
36	Carriage House		LISTED	Classical Revival	2 to 2 1/2 story	rectangle	Mass masonry, concrete floors, brick veneer	Gable	Asphalt/Composite	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Brick	Continuous	Gravel	brick walkway
37	Stables		LISTED	Classical Revival	2 to 2 1/2 story	T-shaped	Mass masonry, concrete floors, brick veneer	Mixed	Asphalt/Composite	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Brick	Continuous	No	horse paddock, manure bin
38	Log Cabin (School)		LISTED	Vernacular	1	rectangle	logs	Gable	Asphalt/Composite	Exposed rafters w/fascia	Wood	Other	Wood	Casement	Brick	Piers w/ no in-fill	No	walkway, mid canopy tree, shrubs
39	Kitchen Garden		LISTED	Formal Landscaping			na										No	perimeter wall, railed masonry
40	Kitchen Garden Shed		LISTED	Classical Revival	1	rectangle	Mass masonry	Gable	Metal Standing seam	flush no overhang	Brick	Running bond	Wood	Casement	Brick	Continuous	No	low canopy trees
41	OC (Overflow) Cottage		LISTED	Colonial Revival	2 to 2 1/2 story	L shape	platform, wood framed	Mixed	Clay flat slab	Boxed Cornice	Wood	Weather board	Wood	Double Hung	Brick	Piers w/in-fill	No	surrounding brick walkway, canopy trellis

Pebble Hill Plantation – Historic Resource Survey

Bldg number	Building Name	Photograph	NRHP	Architectural Style	Number of Stories	Plan Shape	Construction System	Roof Design	Roof Material	Eave	Ext. Wall Material	Type of cladding	Window Material	Type	Foundation Materials	Type of foundation	Driveway	Landscape features
42	Electrical Shed		Eligible	Classical Revival	1	Square	Mass masonry	Gable	Clay flat slab	Boxed Cornice	Brick	Common bond	Wood	Casement	Brick	Continuous	Gravel	
43	Nurse's Office		LISTED	Classical Revival	2 to 2 1/2 story	T-shaped	Mass masonry	Cross Gable	Clay flat slab	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Brick	Continuous	Gravel	low vine coverage on ext. walls, low
44	Fire Engine House		LISTED	Classical Revival	2 to 2 1/2 story	T-shaped	Mass masonry	Cross Gable	Clay flat slab	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Brick	Continuous	Gravel	low vine coverage on ext. walls, low
45	Carpenter's Shop		LISTED	Classical Revival	2 to 2 1/2 story	T-shaped	Mass masonry	Cross Gable	Clay flat slab	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Brick	Continuous	Gravel	low vine coverage on ext. walls, low
46	Dog Hospital		LISTED	Classical Revival	1 to 1 1/2 story	rectangle	Mass masonry	Gable	Clay flat slab	Boxed Cornice	Brick	Running bond	Wood	Double Hung	Concrete (poured)	Slab	No	walkway, fenced dog brick
47	Waldorf		LISTED	Classical Revival	2 to 2 1/2 story	T-shaped	Mass masonry	Gable	Asphalt/Composite	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Concrete (poured)	Slab	Gravel	walkway, vine growth on brick
48	Kennel Cottage		LISTED	Vernacular	1 to 1 1/2 story	rectangle	Mass masonry	Dutch	Asphalt/Composite	Exposed rafters w/fascia	Wood	Board & Batten	Wood	Double Hung	Brick	Piers w/in-fill	No	walkway, low canopy trees hedge on
49	Old Dining Room Shed (restrooms)		LISTED	Vernacular	1 to 1 1/2 story	Square	CMU	Gable	Asphalt/Composite	Boxed Cornice	CMU	Running bond	Vinyl	Double Hung	Concrete (poured)	Slab	No	front and side, concrete
50	Learning Center (Pipe Shed)		LISTED	Vernacular	1 to 1 1/2 story	rectangle	Stick framed	Gable	Asphalt/Composite	Exposed rafters w/fascia	Wood	Ship lap	Wood	Casement	Brick	Continuous	Gravel	walkway and ADA entry
51	Blacksmith's Shop (Shed)		LISTED	Vernacular	1	Square	Stick framed	Gable	Asphalt/Composite	Exposed rafters w/fascia	Wood	Ship lap	Wood	Casement	Concrete (poured)	Continuous	No	no unique features
52	Mule Feeder		Eligible	No Academic Style	1	octagon	post and beam	Pyramid hip	Wood	Exposed rafters w/fascia	Other				Brick	Piers w/ no in-fill	No	nearby large retaining wall
53	Dog Kennel Kitchen		LISTED	Classical Revival	1	L shape	Mass masonry	Gable	Clay flat slab	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Brick	Slab	No	extreme tree/vine encroachment
54	Dog Kennel Annex		LISTED	Classical Revival	1	Square	Mass masonry	Cross Gable	Clay flat slab	Boxed Cornice	Brick	Common bond	Wood	Double Hung	Brick	Slab	No	washing facilities (sinks/concrete brick apron
55	Ticket Booth		LISTED	Classical Revival	1	octagon	Stick framed	Pyramid hip	Wood	flush no overhang	Wood	Weather board	Wood	Double Hung	Concrete (poured)	Slab	Asphalt	and brick pony wall
56	Gatehouse east		LISTED	Classical Revival	2 to 2 1/2 story	rectangle	Mass masonry	Cross Gable	Clay flat slab	Boxed Cornice	Brick	Common Flemish	Wood	Double Hung	Concrete (poured)	Slab	No	walkway, bushes (east hedge along
57	Gatehouse garage		LISTED	Classical Revival	1 to 1 1/2 story	rectangle	Mass masonry	Gable	Clay flat slab	Boxed Cornice	Brick	Running bond	Wood	1/2 Circle	Concrete (poured)	Slab	Asphalt	east and west side, vine
58	Gatehouse west		LISTED	Classical Revival	2 to 2 1/2 story	rectangle	Mass masonry	Cross Gable	Clay flat slab	Boxed Cornice	Brick	Common Flemish	Wood	Double Hung	Concrete (poured)	Slab	No	ornamental trees/shrubs on north side, extensive vine
59	Pump House		LISTED	Classical Revival	2 to 2 1/2 story	rectangle	Mass masonry, concrete, steel	Tray	Asphalt/Composite	flush no overhang	Brick	Common bond	Metal	mixed	Concrete (poured)	Slab	No	growth exterior walls, shrubs,
60	Big Barn Cottage		NO	Colonial Revival	2 to 2 1/2 story	Complex	platform, wood framed	Cross Gable	Mixed	Boxed Cornice	Composite	Weather board	Vinyl	Double Hung	Brick	Piers w/in-fill	Gravel	bushes, brick walkway, mid
61	Oak Post New Stable		NO	No Academic Style	1	Square	pole barn	Flat	Metal corrugated	Exposed rafters no fascia	Other				Wood	Pillings	No	
62	Oak Post Storage		Eligible	Vernacular	2 to 2 1/2 story	rectangle	pole barn	Flared Gable	Metal corrugated	Exposed rafters w/fascia	Wood	Board & Batten			Brick	Piers w/ no in-fill	Gravel	huge oaks to west and north

Pebble Hill Plantation – Historic Resource Survey

Bldg number	Building Name	Photograph	NRHP	Architectural Style	Number of Stories	Plan Shape	Construction System	Roof Design	Roof Material	Eave	Ext. Wall Material	Type of cladding	Window Material	Type	Foundation Materials	Type of foundation	Driveway	Landscape features
63	Oak Post Stable (old)		Eligible	Vernacular	1 to 1 1/2 story	rectangle	pole barn	Flared Gable	Metal corrugated	Exposed rafters no fascia	Wood	Post and Beam w/infill wood			Brick	Piers w/in-fill	No	
64	Oak Post Barn		Eligible	Vernacular	1 to 1 1/2 story	rectangle	Stick framed	Gable	Metal corrugated	Exposed rafters no fascia	Wood	Weather board			Brick	Continuous	No	
65	Uno Hill Chix Coop west		Eligible	Vernacular	1	rectangle	Stick framed	Gable	Mixed	Exposed rafters w/fascia	Wood	Ship lap	Wood	Casement	CMU	Continuous	No	
66	Uno Hill Chix Coop east		Eligible	Vernacular	1	rectangle	Stick framed	Gable	Mixed	Exposed rafters w/fascia	Wood	Ship lap	Wood	Casement	CMU	Continuous	No	
67	Uno Hill Maintenance #1		NO	Vernacular	1 to 1 1/2 story	rectangle	Stick framed	Cross Gable	Asphalt/Composite	Boxed Cornice	Wood	Ship lap			Concrete (poured)	Slab	No	
68	Uno Hill Maintenance #2		NO	Vernacular	1 to 1 1/2 story	rectangle	Stick framed	Cross Gable	Asphalt/Composite	Boxed Cornice	Wood	Ship lap			Concrete (poured)	Slab	No	
69	Uno Hill Maintenance #3		NO	Vernacular	1 to 1 1/2 story	rectangle	Stick framed	Cross Gable	Asphalt/Composite	Boxed Cornice	Wood	Ship lap			CMU	Continuous	No	
70	Uno Stable (kitchen)		NO	Agricultural Revival	1 to 1 1/2 story	rectangle	Stick framed	Flared Gable	Metal corrugated	Exposed rafters no fascia	Wood	Board & Batten	Wood	Casement	Concrete (poured)	Slab	No	
71	Uno Stable (venue)		NO	Agricultural Revival	1 to 1 1/2 story	T-shaped	post and beam	Flared Gable	Metal corrugated	Exposed rafters no fascia	Wood	Board & Batten	Vinyl	Casement	Concrete (poured)	Slab	No	numerous concrete patios and
72	Uno Stable pump house		NO	Vernacular	1	Square	Stick framed	Hip	Metal corrugated	Exposed rafters no fascia	Wood	Board & Batten	Wood	Casement	Concrete (poured)	Slab	No	lawn
73	War Cottage #1		Eligible	Vernacular	1 to 1 1/2 story	T-shaped	platform, wood framed	Hip & Valley	Asphalt/Composite	Boxed Cornice	Wood	Weather board	Vinyl	Double Hung	Brick	Piers w/ no in-fill	Gravel	shrubs, bushes, 2 high canopy tree on north,
74	War Cottage #2		Eligible	Vernacular	1 to 1 1/2 story	rectangle	platform, wood framed	Flared Gable	Asphalt/Composite	Exposed rafters no fascia	Wood	Board & Batten	Wood	Double Hung	Brick	Piers w/ no in-fill	No	concrete low canopy trees in front, lawn, bushes
75	War Cottage #3		Eligible	Vernacular	1 to 1 1/2 story	rectangle	platform, wood framed	Hip	Asphalt/Composite	Exposed rafters w/fascia	Wood	Board & Batten	Wood	Double Hung	Brick	Piers w/ no in-fill	No	ornamental landscape plantings in mid canopy tree on east side, closely
76	War Cottage #4		Eligible	Vernacular	1 to 1 1/2 story	rectangle	platform, wood framed	Flared Gable	Asphalt/Composite	Exposed rafters w/fascia	Wood	Board & Batten	Wood	Double Hung	Brick	Piers w/ no in-fill	No	surrounded by high canopy
77	War Cottage #5		Eligible	Vernacular	1 to 1 1/2 story	rectangle	platform, wood framed	Flared Gable	Asphalt/Composite	Exposed rafters no fascia	Wood	Board & Batten	Wood	Double Hung	Brick	Piers w/ no in-fill	No	lawn
78	War Cottage #6		Eligible	Vernacular	1 to 1 1/2 story	T-shaped	platform, wood framed	Hip & Valley	Asphalt/Composite	Exposed rafters w/fascia	Wood	Weather board	Wood	Double Hung	Brick	Piers w/ no in-fill	No	lawn
79	War Cottage #7		Eligible	Vernacular	1 to 1 1/2 story	rectangle	platform, wood framed	Flared Gable	Asphalt/Composite	Exposed rafters no fascia	Wood	Board & Batten	Wood	Double Hung	Brick	Piers w/ no in-fill	No	lawn
80	War Cottage #8		Eligible	Vernacular	1 to 1 1/2 story	T-shaped	platform, wood framed	Cross Gable	Asphalt/Composite	Exposed rafters w/fascia	Wood	Weather board	Wood	Double Hung	Brick	Piers w/ no in-fill	No	lawn
81	Peachtree Cottage		Eligible	Colonial Revival	1 to 1 1/2 story	T-shaped	platform, wood framed	Hip & Valley	Asphalt/Composite	Boxed Cornice	Wood	Weather board	Vinyl	Double Hung	Brick	Piers w/ no in-fill	Gravel	bushes on south side, mid canopy brick patio
82	Big Pine Wood Cottage		Eligible	Vernacular	1 to 1 1/2 story	rectangle	platform, wood framed	Flared Gable	Asphalt/Composite	Exposed rafters w/fascia	Wood	Board & Batten	Wood	Double Hung	Brick	Piers w/in-fill	Concrete	enclosures on east and west
83	Big Green Shed		Eligible	Vernacular	2 to 2 1/2 story	rectangle	pole barn	Cross Gable	Asphalt/Composite	Exposed rafters no fascia	Wood	Board & Batten	Wood	Double Hung	Brick	Piers w/ no in-fill	No	

Pebble Hill Plantation – Historic Resource Survey

Bldg number	Building Name	Photograph	NRHP	Architectural Style	Number of Stories	Plan Shape	Construction System	Roof Design	Roof Material	Eave	Ext. Wall Material	Type of cladding	Window Material	Type	Foundation Materials	Type of foundation	Driveway	Landscape features
84	Big Green Barn		Eligible	Vernacular	2 to 2 1/2 story	rectangle	post and beam	Gable	Asphalt/Composite	Boxed Cornice	Wood	Board & Batten	Wood	Double Hung	Brick	Continuous	No	
85	Big Green Farmer's Cottage		Eligible	Vernacular	1 to 1 1/2 story	cross	platform, wood framed	Flared Gable	Asphalt/Composite	Exposed rafters no fascia	Wood	Board & Batten	Wood	Double Hung	Brick	Piers w/in-fill	Gravel	shrubs, ADA ramp (worn), metal fencing
86	Big Green Farmer's Cottage Shed		Eligible	Vernacular	1	rectangle	Stick framed	Gable	Asphalt/Composite	Exposed rafters w/fascia	Wood	Board & Batten	Wood	Casement	Concrete (poured)	Slab	No	bushes
87	White Turkey Cottage		Eligible	Vernacular	1 to 1 1/2 story	T-shaped	platform, wood framed	Hip & Valley	Asphalt/Composite	Exposed rafters w/fascia	Wood	Weather board			Brick	Piers w/ no in-fill	No	no features
88	Brer Rabbit Hunters Cabin		Eligible	Vernacular	1 to 1 1/2 story	rectangle	platform, wood framed	Flared Gable	Asphalt/Composite	Exposed rafters no fascia	Wood	Weather board	Mixed	Double Hung	Brick	piers w/no in-fill	No	Mature high canopy trees overhang
89	Sugar Hill Barn (venue)		NO	Agricultural Revival	2	T-shaped	post and beam	Cross Gable	Metal corrugated	Exposed rafters w/fascia	Wood	Board & Batten			Concrete (poured)	Slab	Gravel	perimeter fence
90	Austin House Ruins		Eligible	Former site			na										No	perimeter fence
91	Abandon Cottage #1		Eligible	Vernacular	1 to 1 1/2 story	L shape	platform, wood framed	Hip & Valley	Asphalt/Composite	Boxed Cornice	Wood	Weather board	Wood	Double Hung	Brick	Piers w/ no in-fill	No	na
92	Abandon Cottage #2		Eligible	Vernacular	1 to 1 1/2 story	rectangle	platform, wood framed	Flared Gable	Asphalt/Composite	Exposed rafters w/fascia	Wood	Board & Batten	Wood	Double Hung	Brick	Piers w/ no in-fill	No	
93	Barn near Sugar Hill House		Eligible	Vernacular	1 to 1 1/2 story	rectangle	pole barn	Monitor Barn	Metal corrugated	Exposed rafters no fascia	Wood	Weather board	na		Brick	Piers w/in-fill	No	
94	Sugar Hill House		Eligible	Classical Revival	1 to 1 1/2 story	h-shaped	platform, wood framed	Cross Gable	Clay flat slab	Boxed Cornice	Wood	Weather board	wood	mixed	Brick	piers w/no in-fill	Gravel	shrubs, brick walkway, high canopy trees
95	Sugar Hill House Garage		NO	Agricultural Revival	1	rectangle	pole barn	Flared Gable	Metal corrugated	Exposed rafters w/fascia	wood	Weather board	Wood	Double Hung	Concrete (poured)	Slab	Gravel	
96	Piney Grove Missionary Baptist Church		Eligible	Classical Revival	2 to 2 1/2 story	rectangle	platform, wood framed	Gable	Asphalt/Composite	boxed cornice + tray	Wood	Weather board	Mixed	Mixed	Brick	Continuous	No	
97	Piney Grove Fellowship Hall		NO	Vernacular	1 to 1 1/2 story	Square	CMU	Cross Gable	Asphalt/Composite	boxed cornice	CMU	Running bond	Vinyl	Double Hung	Concrete (poured)	Continuous	No	
98	Piney Grove Maintenance Shed		NO	Vernacular	1	Square	Fabricated	Gable	Metal corrugated								No	
99	Pet Cemetery		Eligible	Formal Landscaping			na										No	perimeter metal fence (old), site of 6 former dog pens, 3 still
100	Dog Kennel Pens		Eligible	Formal Landscaping			na										No	
101	Sugar Hill Barn (venue) garage		NO	Agricultural Revival	1	Square	Stick framed	Gable	Metal corrugated	Exposed rafters w/fascia	Wood	Sheet material	Vinyl	Double Hung	Concrete (poured)	Slab	Concrete	
102	Sugar Hill Barn (venue) pump house		NO	Agricultural Revival	1	Square	Stick framed	Gable	Metal corrugated	Exposed rafters w/fascia	Wood	Sheet material			Concrete (poured)	Slab	Concrete	
103	Sugar Hill House Pump House		NO	Colonial Revival	1	rectangle	Stick framed	Cross Gable	Asphalt/Composite	Exposed rafters w/fascia	Wood	Weather board	Wood	Casement	Concrete (poured)	Slab	Gravel	concrete walkway
104	Sugar Hill House 3 Bay Garage		Eligible	Colonial Revival	1 to 1 1/2 story	rectangle	pole barn	Flared Gable	Asphalt/Composite	Exposed rafters w/fascia	Wood	Weather board	Wood	Casement	Concrete (poured)	Slab	Gravel	concrete walkway in rear

Pebble Hill Plantation – Historic Resource Survey

Bldg number	Building Name	Photograph	NRHP	Architectural Style	Number of Stories	Plan Shape	Construction System	Roof Design	Roof Material	Eave	Ext. Wall Material	Type of cladding	Window Material	Type	Foundation Materials	Type of foundation	Driveway	Landscape features
105	Sugar Hill House Storage Shed		Eligible	Colonial Revival	1	Square	Stick framed	Flared Gable	Asphalt/Composite	Exposed rafters w/fascia	Wood	Weather board	Wood	Casement	Concrete (poured)	Slab	Gravel	concrete walkway in rear